THE PORT AUTHORITY OF NY & N.J.

September 1, 2016

United States Environmental Protection Agency Air Compliance Branch 290 Broadway, 21st Floor New York, NY 10007-1866

Attn:

NESHAP COORDINATOR

Re:

LAGUARDIA AIRPORT -BUILDING #: 30,

FORMER PORT AUTHORITY POLICE BUILDING.

OPERATOR PROJECT #: 217.854

Dear Madam/Sir:

Our Non-RACM courtesy notification for the asbestos abatement work to be done at the above referenced location is attached.

If you have any questions, please contact me at 201-595-4881.

Sincerely,

Uday Mehta, Manager

Environmental field Operations

Construction Management Division

cc:

Project File (EPA-2477)

NON-RACM Notification File

UM/fl

U.S. Environmental Protection Agency Notification of Demolition and Renovation

Operator Project #: 217.854	Postmark:		Date Received:	09/01/2016	Notification	#: EPA-24	77	
Type of Notification (O=Original R=Revised C=Canceled) O								
II. Facility Information (Identify owner, removal contractor, and other operator)								
Owner Name: THE PORT AUTHORITY OF NY & NJ								
Address: 241 ERIE S	241 ERIE ST. ROOM 236							
City: JERSEY CI	JERSEY CITY State: NJ				Zip: 07310			
Contact: F.DAMBRE					Telephone:	718-533-4	4053	
Removal Contractor: NEW YORK ENVIRONMENTAL SYSTEMS								
Address: 368 RICHA	368 RICHARD STREET							
City: BROOKLYN	BROOKLYN State: NY				Zip: 11222	Zip: 11222		
Contact: ROBERT PA	ROBERT PAVLOVICH Telephone: 718-302-3500					3500		
Other operator: N/A	·							
Address:								
City:	State:					Zip:		
Contact:					Telephone:			
III. Type of Operation (D=Demo O=Ordered Demo R=Renovation E=Emergency) R								
IV. Is Asbestos Present? (Yes/No) YES								
		nber, floor, and	l /or room numb	er):				
V. Facility Description (include building name, number, floor, and /or room number): Building Name: LAGUARDIA AIRPORT								
Address: LAGUARDIA								
City: FLUSHING								
	Outry.							
Building Size: N/A		# of Floors:2 Age in Years:30+						
Present Use: VACANT		Prior Use: OFFICE SPACE						
VI. Procedure, Including Analytical Method, If Appropriate, Used to Detect the Presence of Asbestos Material:								
BULK SAMPLING WITH TEM ANALYSIS								
VII. Approximate Amount of Asbe				Nonfriable Asbestos Materials Not To Be Removed				
Regulated ACM to be Removed Category I ACM Not Removed		Non-RACM To Be Removed	RACM to Be Removed		THOU TO BE ITEMIOVED		Indicate Measurement	
3. Category II ACM Not Ren	noved		Do riomovou	Cat I	Cat II	cacaromont		
Pipes ELECTRICAL WIRE INSULATION		00 LN.FT			·	Lnft: 2,	,900	
Surface Area VAT,MASTIC,TRANSITE		50 SQ.FT.				Sqft: 6,	,550	
Vol RACM Off Facility Component Cuft: 0				0				
VIII. Scheduled Dates Asbestos Removal Start: 9/16/2016 Complete: 12/30/2016								
IX. Scheduled Dates Demo\Renovation Start: Complete:								

U.S. Environmental Protection Agency Notification of Demolition and Renovation

X. Description of Planned Demolition or Renovation Work, and Method(s) to Be Used: REMOVAL USING WET METHOD WITH SURFACE AND ISOLATION BARRIERS							
XI. Description of Work Practices and Engineering Controls to Be Used to Prevent Emissions Of Asbestos At the Demolition And Renovation Site: DUST CONTROL USING WET METHOD ISOLATION AND SURFACE BARRIER, ENGINEERING CONTROL USING VACUUMS EQUIPPED WITH HEPA FILTERS. WET REMOVAL AS PER NEW YORK STATE INDUSTRIAL CODE RULE 56.							
XII. Waste Trai	nsporter #1						
Name:	ASBESTOS TRANSPORATION COMPANY, INC.						
Address:	2 MORICHES MIDDLE ISLAND ROAD						
City:	SHIRLEY	State: NY	Zip: 11967				
Contact:	GARY GRETTY		Telephone: 631-924-5050				
Waste Trai	nsporter #2						
Name:	N/A						
Address:							
City:		State:	Zip:				
Contact:			Telephone:				
XIII. Waste Dis	posal Site						
Name:	MEADOWFILL LANDFILL, INC.						
Location:	ROUTE 2, BOX 68						
City:	BRIDGEPORT	State: WV	Zip: 26330				
Telephon	e:304-842-2784						
XIV. If Demolit	ion Ordered By a Government Agency, Please Ident	ify the Agency Below	*				
Name:	Title:						
Authority							
Date of O	rder:	Date Ordered 1	o Begin:				
XV. For Emergency Renovations							
Date and Hour of Emergency:							
Description of Sudden or Unexpected Event:							
	•						
Explanation of How the Event Caused Unsafe Conditions or Would Cause Equipment Damage or an Unreasonable Financial Burden:							
XVI. Descriptions of Procedures to Be Followed in the Event That Unexpected Asbestos Is Found or Previously Nonfriable Asbestos Material Becomes Crumbled, Pulverized or Reduced to Powder: IMMEDIATE ISOLATION OF THE AREA AND ADEQUATE WETTING OF ASBESTOS MATERIAL FOLLOWED BY HEPA VACUUMING AND WET WIPING ALL AFFECTED AREAS							
XVII. I Certify That an Individual Trained in the Provisions of This Regulation (40 CFR Part 61, Subpart M) Will Be On-Site During the Demolition or Renovation And Evidence That the Required Training Has Been Accomplished by This Person Will Be Available for inspection (Signature of Cwper/Operator) (Date)							
XVIII. I Cerify TI	nat the Above Information Is Correct.	Signature of Owner/Opera	ator) 090/-/6				